



Squeezing Cum Densifier Machine



Problems.....?

- Drying Problem in Monsoon...?
- Dust is Deposited on the Washed Material...?
- It needs lots of space for drying...?
- Around 6 Persons are required for handling the waste of nearly 3 MT...?
- Around 5% of Material is lost due to manual handling...?

Benifits :

- Only One Person Instead of 5 labour
- 3' x 6' Space & Mini.3 MT/day Drying
- Space Saving & Easy to Operate
- Drying Possible day/night and very help full in a Monsoon season. Water Separate with Squeezing System
- Material is Semi melt through one Heater &
- You can get densifier Materials (No need agglo after Drying Material)

Here is the Solution...

Suitable for PE Film (Grinded material)
Moisture 2% to 3% Only.

Model No.	Main Motor H.P.	Out put Kgs/hr
SD-40	40	100 to 125
SD-60	60	150 to 225
SD-90	90	250 to 400

*Capacity Depend on Material & Feeding System